




Lumos!

4. Place copper tape on "switch".




1. Place copper tape on first leg

2. Tape coin battery on dot with + side facing up.

3. Place copper tape on second leg starting on top of the + side of the battery.

5. Place copper tape on second leg







Lumos!